

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



Photo 1 – Generator – Overgrown Vegetation

Photo 2 – Generator – Overgrown Vegetation

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



ECMC
40.63913, -104.27678, 4954.0ft
10/04/2023 14:12:39



ECMC
40.63889, -104.27657, 4953.7ft
10/04/2023 14:12:55

Photo 3 – Pumping Unit – Overgrown Vegetation

Photo 4 – Stained Soil – Wellhead

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



Photo 5 – Overgrown Vegetation



Photo 6 – Stained Soil

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



Photo 7 – Wildlife Netting Missing



Photo 8 – Overgrown Vegetation at ECD and Gas Meter House

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



Photo 9 – Overgrown Vegetation at Heater Treater and Propane Tank

Photo 10 – Overgrown Vegetation at Heater Treater and Propane Tank

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



Photo 11 – Overgrown Vegetation at Heater Treater and Propane Tank



Photo 12 – Overgrown Vegetation at Tank Battery

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



Photo 13 – Tank Battery Signs

Photo 14 – Overgrown Vegetation at Tank Battery

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



Photo 15 – Unmanaged Weeds in Interim Reclamation Area

Photo 16 – Unmanaged Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Cass Farms 11-25H-8-62
Location ID: 420020



Photo 17 – Unmanaged Weeds in Interim Reclamation Area

Photo 18 – Unmanaged Weeds in Interim Reclamation Area