

Final Reclamation Inspection

September 28th, 2023

Operator: Simcoe LLC -10749

Location ID: 325351

Inspection Document #: 714000033

La Plata County, CO

Township: SENW 16 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Craig 1 & 3
Location ID: 325351



Photo 1. Overview of the disturbance taken from the western edge of the disturbance facing east. Note: two wells share a disturbance at this location.



Inspection Photos
Location Name: Craig 1 & 3
Location ID: 325351



Photo 2. Photo of the southern fill slope interim area facing west.



Inspection Photos
Location Name: Craig 1 & 3
Location ID: 325351



Photo 3. Photo of the western fill slope interim area facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06223, 09732

Inspection Photos
Location Name: Craig 1 & 3
Location ID: 325351



Photo 4. Photo of eastern interim area facing north. Note: eastern edge opens up to grazing pasture to the east of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06223, 09732

Inspection Photos
Location Name: Craig 1 & 3
Location ID: 325351



Photo 5. Photos of rill and gully erosion forming along western fill slope interim area.

Inspection Photos
Location Name: Craig 1 & 3
Location ID: 325351



Photo 6. Musk thistle and Chicory observed flowering in various locations throughout the disturbance.

Inspection Photos
Location Name: Craig 1 & 3
Location ID: 325351



Photo 7. Undesirable weeds/debris surrounding active equipment.