

Final Reclamation Inspection

September 28th, 2023

Operator: BP American Production Company -
10000

Location ID: 385631

Inspection Document #: 714000034

La Plata County, CO

Township: NWSE 33 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Photo 1. View of the project area taken from the northern edge facing center.

Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Photo 2. View of unknown equipment in the northern cutslope of the project area.

Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Photo 3. View of the project area taken from the southern edge facing center. Vegetation within project area is progressing towards 80% vegetation thresholds.



Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Photo 4. Unknown debris located on western edge of project area.



Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Photo 5. Unknown equipment remains on the western edge of the project area.