

Inspection Photos

Location Name: North Lost Creek-63N62W 17SWSE Tank Battery

Location ID: 331746



Sign



Overgrown Vegetation



Inspection Photos

Location Name: North Lost Creek-63N62W 17SWSE Tank Battery

Location ID: 331746



Location and Overgrown vegetation



Unused hose

Inspection Photos

Location Name: North Lost Creek-63N62W 17SWSE Tank Battery

Location ID: 331746



Unused equipment



Unmarked Riser

Inspection Photos

Location Name: North Lost Creek-63N62W 17SWSE Tank Battery

Location ID: 331746



Unused hose



Unmarked riser

Inspection Photos

Location Name: North Lost Creek-63N62W 17SWSE Tank Battery

Location ID: 331746



Stained soil

