

Inspection Photos
Location Name: Siefken 11-30H
Location ID: 424135



Photo 1 – Pumping Unit



Photo 2 – Wellhead – Overgrown Vegetation and Stained Soil

Inspection Photos
Location Name: Siefken 11-30H
Location ID: 424135



Photo 3 – Gas Engine



Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Siefken 11-30H
Location ID: 424135



Photo 5 – Stained Soil at Gas Engine



Photo 6 – Overgrown Vegetation

Inspection Photos
Location Name: Siefken 11-30H
Location ID: 424135



Photo 7 – Tank Battery – Overgrown Vegetation



Photo 8 – Tank Battery – Overgrown Vegetation



Inspection Photos
Location Name: Siefken 11-30H
Location ID: 424135



Photo 9 – Tank Battery Signs



Photo 10 – Overgrown Vegetation Separator