


## Inspection Photos

Location Name: HSR-LOST CREEK-63N62W 14NWSW Tank Battery

Location ID: 330171



**Sign & Overgrown Vegetation**



**Overgrown Vegetation**

## Inspection Photos

Location Name: HSR-LOST CREEK-63N62W 14NWSW Tank Battery

Location ID: 330171



**Overgrown Vegetation**



**Overgrown Vegetation**





## Inspection Photos

Location Name: HSR-LOST CREEK-63N62W 14NWSW Tank Battery

Location ID: 330171



**Overgrown Vegetation**



**Overgrown Vegetation**



## Inspection Photos

Location Name: HSR-LOST CREEK-63N62W 14NWSW Tank Battery

Location ID: 330171



**Overgrown Vegetation**



**Overgrown Vegetation**





## Inspection Photos

Location Name: HSR-LOST CREEK-63N62W 14NWSW Tank Battery

Location ID: 330171



**Overgrown Vegetation**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources