

Inspection Photos
Location Name: Foose USX/A18-23
Location #: 420665



Photo #1
Foose A18-23 Battery site
Inactive / Shut-down
Formerly served:
Foose A18-9, Foose A18-10 ;
Plugged & Abandoned | PA



Photo #2
Foose A18-9 Battery site
Inactive / Shut-down
Tank(s): SE corner



Inspection Photos
Location Name: Foose USX/A18-23
Location #: 420665



Photo #3
Foos A18-23 Battery site
Inactive / Shut-down
Separator(s), ECD(s)



Photo #4
Foos A18-9 Battery site
Inactive / Shut-down
Battery sign



Inspection Photos
Location Name: Foose USX/A18-23
Location #: 420665



Photo #5
Foose A18-23 (123-32666) Wellsite
Temporarily Abandoned | TA

