

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2023

Submitted Date:

10/11/2023

Document Number:

701007484

FIELD INSPECTION FORM

Loc ID 321821 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208112	WELL	TA	08/03/2023	OW	017-07047	HARKER 34-35 1X	PA

General Comment:

[P&A Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Elevated gravel road through pasture		
Corrective Action:		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 208112 Type: WELL API Number: 017-07047 Status: TA Insp. Status: PA

Cement

Cement Contractor

Contractor Name: HP Oilfield Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2392/1804/584

Cement Volume (sx): 420 SXS

Good Return During Job: _____

Cement Type: 60/40 POZ W/4% GEL

Comment: HALDE WATER, CODELL WELL SERVICE, HP OILFIELD SERVICE. MIRU CODELL, RIH W/CICR TO 2392'. MIRU HP, PUMP 60 SXS CMT THRU W/30 SXS ON TOP. MIRU CODELL, POOH W/TBG, RIH W/CICR TO 1804'. MIRU HP, PUMP 40 SXS THRU W/5 SXS ON TOP. MIRU CODELL, POOH W/TBG. MIRU HP, PUMP 20BBLS WATER AHEAD WITH BLOW ON ANNULUS, PUMP 275 SXS W/600 PSI, LOST CIRC. SHUT DOWN. RIG UP TO BRADENHEAD, PUMP 10 SXS W/500 PSI.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment: [Location is grassed over and access is partially grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT