

Inspection Photos
Location Name: Dutch Lake 16-24H PAD
Location ID: 422838



Photo 1 – Wellheads



Photo 2 – Pumping Units



Inspection Photos
Location Name: Dutch Lake 16-24H PAD
Location ID: 422838



Photo 3 – Wellhead



Photo 4 – Pumping Unit



Inspection Photos
Location Name: Dutch Lake 16-24H PAD
Location ID: 422838




Photo 5 – Heater Treater – Weeds



Photo 6 – Gas Meter Houses

Inspection Photos
Location Name: Dutch Lake 16-24H PAD
Location ID: 422838



Photo 7 – Unmarked Riser at Separators



Photo 8 – Area East of Separators

Inspection Photos
Location Name: Dutch Lake 16-24H PAD
Location ID: 422838



Photo 9 – Separators



Photo 10 – Stained Soil and Unmarked Riser

Inspection Photos
Location Name: Dutch Lake 16-24H PAD
Location ID: 422838




Photo 11 – Unmarked Riser



Photo 12 – Tank Labels

Inspection Photos
Location Name: Dutch Lake 16-24H PAD
Location ID: 422838



Photo 13 – Stained Soil and Oily Waste at Pumping Unit



Photo 14 – VRT

Inspection Photos

Location Name: Dutch Lake 16-24H PAD
Location ID: 422838



Photo 15 – Tank Battery



Photo 16 – Tank Battery Signs

Inspection Photos
Location Name: Dutch Lake 16-24H PAD
Location ID: 422838



Photo 17 – Overgrown Vegetation



Photo 18 – Overgrown Vegetation