

Inspection Photos

Location Name: Circle B Rudd 6-61-18-0263BH2

Location ID: 438823



Photo 1 – Wellhead

Photo 2 – Line Heater

Inspection Photos

Location Name: Circle B Rudd 6-61-18-0263BH2

Location ID: 438823



Photo 3 – Flare

Photo 4 – ECDs

Inspection Photos

Location Name: Circle B Rudd 6-61-18-0263BH2

Location ID: 438823



Photo 5 – Tumbleweeds at Berm

Photo 6 – Tank Battery Signs

Inspection Photos
Location Name: Circle B Rudd 6-61-18-0263BH2
Location ID: 438823



Photo 7 – Tumbleweeds at Berm

Photo 8 – Stained Soil and Tumbleweeds

Inspection Photos

Location Name: Circle B Rudd 6-61-18-0263BH2

Location ID: 438823



Photo 9 – Tumbleweeds at Berm

Photo 10 – Tumbleweeds at Berm

Inspection Photos

Location Name: Circle B Rudd 6-61-18-0263BH2

Location ID: 438823



Photo 11 – VRT and Separators

Photo 12 – Tumbleweeds at Separator

Inspection Photos

Location Name: Circle B Rudd 6-61-18-0263BH2

Location ID: 438823



Photo 13 – Gas Meter House

Photo 14 – VRU

Inspection Photos

Location Name: Circle B Rudd 6-61-18-0263BH2

Location ID: 438823



Photo 15 – Capacity Label