

# Inspection Photos

10/09/2023

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 335518

**Inspection Doc:** 696205334

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335518



**Photo 1:** Photos 1-2 taken from west end of the working pad surface. Photos provide an overview of the pad from north, northeast, southeast to south.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335518



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335518



**Photo 3:** Photo taken from the central areas of the Location, facing north. Photo example showing marked anchors on the Location, and the wells.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources





**Photo 4:** Photos example of trash/debris, unused pipe, etc... observed on the Location (wellheads, battery).



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335518



**Photo 5:** Photo taken from the separator equipment, facing east. Photo shows flowline riser associated with the abandoned 21A-24D well remaining on the Location.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335518



**Photo 6:** Tank battery facility, south end of the Location. Tank battery signage not posted pursuant to Rule 605.e



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335518



**Photo 7:** Photos examples showing the interim areas of the Location.