

Inspection Photos
Location Name: WPF III-66N64W/18NWNE
Location #: 323559



Photo #1
WPF III A18-2 (123-13195) Wellsite
Temporarily Abandoned | TA
CA: Overgrown Vegetation
prior photo



Photo #2
WPF III A18-2 Wellsite
Temporarily Abandoned | TA
Overgrown Vegetation: Mitigated



Inspection Photos

Location Name: WPF III-66N64W/18NWE

Location #: 323559



Photo #3

WPF III A18-2 Battery site

Inactive / Shut-down

Formerly served:

WPF III A 18-7, Carlson A18-17;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 323559

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources