

**Inspection Photos**  
**Location Name: Harrison 4**  
**API: 05-061-06020**



**Wellhead**



**Treater with pipe hanging from  
the top**

**Insp #701007512 performed in accordance with Complaint Doc #403555060**



**Inspection Photos**  
**Location Name: Harrison 4**  
**API: 05-061-06020**



**South side of tank battery**



**North side of tank battery and  
circulating pump with catch  
basin**

**Insp #701007512 performed in accordance with Complaint Doc #403555060**