

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad
Location # 324247



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 34 6S92W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad
Location # 324247



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad
Location # 324247



Photo # 2220 Erosion & transport of sediment off location/insufficient BMP's (SE corner of location near tank battery containment)



Photo # 2221 Erosion & transport of sediment off location/insufficient BMP's (SE corner of location near tank battery containment)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad
Location # 324247



Photo # 2222 Erosion & transport of sediment off location/insufficient BMP's (SE corner of location near tank battery containment)

Photo # 2223 Erosion & transport of sediment off location/insufficient BMP's (SE corner of location near tank battery containment)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad
Location # 324247



Photo # 2224 Erosion & transport of sediment on slope (SE side of location behind tank battery containment)



Photo # 2225 Erosion & transport of sediment off location/insufficient BMP's (SE side of location behind tank battery containment)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad
Location # 324247



Photo # 2226 Erosion & transport of sediment off location/insufficient BMP's (SE side of location behind tank battery containment)



Photo # 2227 Erosion & transport of sediment off location/insufficient BMP's (SE side of location behind tank battery containment)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC LAST DANCE 9-3 Pad
Location # 324247



**Photo # 2228 Erosion & transport of sediment off location
(N/NE side of location in multiple areas)**