

Operator: 8 North

Location Name: DF RANCH 1161-9-24 TANK

Loc ID: 431338

Inspection: 696305304



Exhibit A

CA: 100 BBL Vault missing Capacity Label; see photos Install signs to comply with Rule 605.h.

CA Resolution: Operator installed missing 100 BBL vault capacity label to comply with rule 605.h.