

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32SWNE

Location ID: 335241

Date: 10/13/2023



Location Entrance – Photo #06927



Wellheads – Photo #06928

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32SWNE

Location ID: 335241

Date: 10/13/2023



Separators – Photo #06930



Tank Battery – Photo #06932

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32SWNE

Location ID: 335241

Date: 10/13/2023



Unsecured Hatch on Separator– Photo #06931

