

Simcoe Le Platt B1: Location ID/API #:067-08931



Photo #1 View of the posted well location signage.

Simcoe Le Platt B1: Location ID/API #:067-08931



Photo #2 Overview of the well location.

Simcoe Le Platt B1: Location ID/API #:067-08931



Photo #3 View of the production equipment.

Simcoe Le Platt B1: Location ID/API #:067-08931



Photo #4 View of the wellhead assembly.

Simcoe Le Platt B1: Location ID/API #:067-08931



Photo #5 View of the pumpjack.

Simcoe Le Platt B1: Location ID/API #:067-08931



Photo #6 View of impacted material at muffler outlet.

Simcoe Le Platt B1: Location ID/API #:067-08931



Photo #7 View of impacted material at muffler.

Simcoe Le Platt B1: Location ID/API #:067-08931



Photo #8 View of impacted material at muffler.