

# Interim and Stormwater Inspection

October 9, 2023

Operator: Investment Equip. LLC, #10330

Location ID: 319632

Inspection Document #:709400524

Adams county, CO

SWSE, Section 22, 2S 57W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1. Photo taken facing southwest, of well head associated with tank battery in previous photos.**



Oct 9, 2023 at 1:16:51 PM  
Fort Morgan CO 80701  
United States



**Photo 2. Photo taken facing west of well head.**

Oct 9, 2023 at 1:16:55 PM  
Fort Morgan CO 80701  
United States



**Photo 3. Photo taken facing north of perennial grasses and weeds (kochia) on working pad perimeter.**



## Inspection Photos

Location Name: Clifford Causey #10 & Tank Battery

Location ID: 319632

Oct 9, 2023 at 1:18:03 PM  
Fort Morgan CO 80701  
United States



**Photo 4. Photo taken facing southwest of perennial grasses and weeds (kochia) on working pad perimeter and in reclaimed area.**

Sep 7, 2023 at 3:13:31 PM  
Fort Morgan CO 80701  
United States



**Photo 5. Photo taken facing north of access road to well head. Stormwater erosion caused gulying in the road way.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400524



Location Name: Clifford Causey #10 & Tank Battery

Location ID: 319632

Sep 7, 2023 at 2:58:50 PM  
Fort Morgan CO 80701  
United States



**Photo 6.** Photo taken of location sign.  
Tank battery ID 319632.

Sep 7, 2023 at 2:59:04 PM  
Fort Morgan CO 80701  
United States



**Photo 7.** Photo taken of battery, facing south. This  
is an off location tank battery.



## Inspection Photos

Location Name: Clifford Causey #10 & Tank Battery

Location ID: 319632

Sep 7, 2023 at 3:01:10 PM  
Fort Morgan CO 80701  
United States



**Photo 8. Photo taken facing north of vegetation and weeds (kochia & russian thistle) between tank battery and pits on location.**

Sep 7, 2023 at 3:02:48 PM  
Fort Morgan CO 80701  
United States



**Photo 9. Photo taken facing south, of stormwater caused gully at gate to pit area.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400524



# Inspection Photos

Location Name: Clifford Causey #10 & Tank Battery

Location ID: 319632

Sep 7, 2023 at 3:04:41 PM  
Fort Morgan CO 80701  
United States



**Photo 10. Photo taken facing southeast, of pit and weeds kochia & russian thistle) along pit perimeter and on the surrounding berm.**

Sep 7, 2023 at 3:05:06 PM  
Fort Morgan CO 80701  
United States



**Photo 11. Photo taken facing northeast, of weeds (kochia) and stormwater caused erosion in un-stabilized pit berm leading into pit.**



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 709400524



## Inspection Photos

Location Name: Clifford Causey #10 & Tank Battery

Location ID: 319632

Sep 7, 2023 at 3:04:24 PM  
Fort Morgan CO 80701  
United States



**Photo 12.** Photo taken facing north, of weeds (kochia) and stormwater caused erosion in un-stabilized pit berm

Sep 7, 2023 at 3:07:53 PM  
Fort Morgan CO 80701  
United States



**Photo 13.** Photo taken facing southwest, of perennial grasses outside of reclaimed area, for reference vegetation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400524