

# Interim and Stormwater Inspection

October 9, 2023

Operator: Fritzler Resources Inc. LLC, #31257

Location ID: 319991

Inspection Document #:709400540

Adams county, CO

NESW, Section 15, 1S 57W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources



Photo 1. Photo taken of location sign, facing north

## Inspection Photos

Location Name: Harold K. Schug #1 & Tank Battery

Location ID: 319991

Oct 9, 2023 at 12:15:13 PM  
Fort Morgan CO 80701  
United States



**Photo 2. Photo taken of tank battery, facing north.  
Bare un-stabilized soil on site.**

Oct 9, 2023 at 12:21:04 PM  
E 144th Ave  
Fort Morgan CO 80701  
United States



**Photo 3. Photo taken of inadequate tank battery  
berm, facing northwest.**



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 709400540

Inspection Photos

Location Name: Harold K. Schug #1 & Tank Battery

Location ID: 319991



**Photo 4. Photo taken of produced water tank and pit, facing east.**



**Photo 5. Photo taken facing southeast of weeds (kochia), and bare soil around pit and tank.**

Inspection Photos

Location Name: Harold K. Schug #1 & Tank Battery

Location ID: 319991



**Photo 6. Photo taken facing southwest, of weeds (kochia & russian thistle) and eroding bare soil around pit.**



**Photo 7. Photo taken facing southwest of weeds (kochia & russian thistle) and bare eroding soil around second pit**



Inspection Photos

Location Name: Harold K. Schug #1 & Tank Battery

Location ID: 319991

Oct 9, 2023 at 12:18:50 PM  
E 144th Ave  
Fort Morgan CO 80701  
United States



**Photo 8. Photo taken facing west of weeds (kochia & russian thistle) and bare soil on pit berm area.**

Oct 9, 2023 at 12:18:52 PM  
E 144th Ave  
Fort Morgan CO 80701  
United States



**Photo 9. Photo taken facing northwest of weeds (kochia & russian thistle), and surrounding undisturbed area.**

Inspection Photos

Location Name: Harold K. Schug #1 & Tank Battery

Location ID: 319991



**Photo 10.** Photo taken facing south of break in containment berm around separator and produced water tank.



**Photo 11.** Photo taken facing east of inadequate tank battery berm.

Inspection Photos

Location Name: Harold K. Schug #1 & Tank Battery

Location ID: 319991

Oct 9, 2023 at 12:23:47 PM  
E 144th Ave  
Fort Morgan CO 80701  
United States



**Photo 12. Photo taken of weeds (kochia & russian thistle) facing north, in interim reclaimed area (well pad)**

Oct 9, 2023 at 12:24:14 PM  
Fort Morgan CO 80701  
United States



**Photo 13. Photo taken of mowed area around well head facing north in interim reclaimed area. (Well Pad)**



Inspection Photos

Location Name: Harold K. Schug #1 & Tank Battery

Location ID: 319991

Oct 9, 2023 at 12:24:16 PM  
Fort Morgan CO 80701  
United States



Oct 9, 2023 at 12:24:19 PM  
Fort Morgan CO 80701  
United States



**Photo 14.** Photo taken facing southeast of mowed interim reclaimed area. (well pad)

**Photo 15.** Photo taken facing northeast of mowed interim reclaimed area. (well pad)



Inspection Photos

Location Name: Harold K. Schug #1 & Tank Battery

Location ID: 319991

Sep 7, 2023 at 4:13:55 PM  
Fort Morgan CO 80701  
United States



**Photo 16. Photo taken facing east of forage for reference vegetation comparison.**