

Final Reclamation Inspection

September 13, 2023

Operator: Noble Energy # 100322

Location ID: 459428

Inspection Document #:709400588

Weld, County CO

NWNW, Section 11 3N67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Bebe Draw 3-14
Location ID: 459428

Sep 13, 2023 at 12:39:27 PM
La Salle CO 80645
United States



Photo 2. Photo taken facing northeast of entrance of new pad construction.

Inspection Photos
Location Name: Bebe Draw 3-14
Location ID: 459428



Photo 3. Photo taken of taken facing east of trackwalked topsoil stockpile on the south side of location.



Photo 4. Photo taken of taken facing east of trackwalked topsoil stockpile on the south side of location.

Inspection Photos
Location Name: Bebe Draw 3-14
Location ID: 459428



Photo 5. Photo taken of topsoil stockpile on south side of location and interior perimeter ditch. Photo taken facing east.



Photo 6. Photo taken of topsoil stockpile on south side of location and exterior perimeter ditch to keep stormwater from coming on to location. Photo taken facing east.

Inspection Photos
Location Name: Bebe Draw 3-14
Location ID: 459428

Sep 13, 2023 at 12:41:28 PM
La Salle CO 80645
United States



Photo 7. Photo taken of wattles at edge of disturbance on the south side of location. Photo taken facing east.

Sep 13, 2023 at 12:43:27 PM
La Salle CO 80645
United States



Photo 8. Photo taken of trackwalked topsoil stockpile on east side of pad. Photo taken facing North.



Inspection Photos
Location Name: Bebe Draw 3-14
Location ID: 459428



Photo 9. Photo taken of large sediment trap in northeast corner of pad. Photo taken facing north.



Photo 10. Photo taken of large sediment trap in northeast corner of pad. Photo taken facing southwest.

Inspection Photos
Location Name: Bebe Draw 3-14
Location ID: 459428

Sep 13, 2023 at 12:47:30 PM
La Salle CO 80645
United States



Photo 11. Photo taken of trackwalked topsoil stockpile on north side of location Photo taken facing west.

Sep 13, 2023 at 12:47:44 PM
La Salle CO 80645
United States



Photo 12. Photo taken of trackwalked topsoil stockpile and interior stormwater ditch on north side of location. Photo taken facing west.

Inspection Photos
Location Name: Bebe Draw 3-14
Location ID: 459428



Photo 13. Photo taken of pad under construction, photo taken facing south.



Photo 14. Photo taken of pad and proposed drilling wells, pad under construction. Photo taken facing south.

Inspection Photos
Location Name: Bebe Draw 3-14
Location ID: 459428

Sep 13, 2023 at 12:49:31 PM
La Salle CO 80645
United States



Photo 15. Photo taken of cut slope west side of pad and interior perimeter ditch. Photo taken facing south.

Sep 13, 2023 at 12:49:55 PM
La Salle CO 80645
United States



Photo 16. Photo taken of access road and wattles on west side of location. Photo taken facing south.