

Interim Reclamation and Stormwater Inspection

October 11, 2023

Operator: CCRP OPERATING INC - #10665

Location ID: 418853

Inspection Document #: 697504897

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lion Creek 4-16H
Location ID: 418853



Photo 1. Photo taken from the eastern interim reclamation area, facing South. Photo illustrates interim reclamation has been performed and perennial vegetation was observed.

Location appears to be recently mowed.



Photo 2. Photo taken from the eastern interim reclamation area, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Lion Creek 4-16H
Location ID: 418853



Photo 3. Photo taken from the southwestern interim reclamation area, facing South. See comments under Photo 1.



Photo 4. Photo taken from the western interim reclamation area, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Lion Creek 4-16H
Location ID: 418853



Photo 5. Photo taken from one of the tank battery signs. Signage is not accurate to reflect the current Operator.



Photo 6. Photo taken of the secondary containment berm, facing South. Secondary containment is inadequate to contain 150% of the volume of the largest tank.

Inspection Photos
Location Name: Lion Creek 4-16H
Location ID: 418853



Photo 7. Weld County aerial imagery taken in 2022 illustrating the area that appears to be related to the 2019 spill.