



99999999

COLO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	
API No. 05- <u>123-08240</u>	LEASE NAME: <u>Sekich #1</u>
LOCATION: <u>NWNE-S19-3N6W</u>	OPERATOR: <u>Amoco Prod</u>
DATE: <u>4-20-98</u>	INSPECTOR: <u>Pavelke</u>
Insp. Type: <u>PR</u>	Insp. Status: <u>PR</u>
PA: Y N	Pass/Fail: <u>P</u> F
Viol.: Y <u>N</u>	NOV: Y <u>N</u>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	<u>up</u>	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	<u>tank</u>	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)	<u>OK</u>	
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)	<u>good</u>	
General Housekeeping (Rule 603)	<u>OK</u>	
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

RECEIVED
APR 21 1998
COLO. OIL & GAS CONS. COMM.

CORRECTIVE ACTION REQUIRED:



00109008

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.