

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 2875 From entrance to location



Photo # 2876 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 2877 Location



Photo # 2878 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 2879 Location



Photo # 2880 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 2881 PRV lacks vent line



Photo # 2882 PRV lacks vent line