

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2023

Submitted Date:

10/19/2023

Document Number:

699107634

FIELD INSPECTION FORMLoc ID 437845 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437836	WELL	PR	05/01/2018	OW	123-39723	Dale 4E-20H-O264	PR
437837	WELL	PR	03/15/2015	OW	123-39724	Dale 4B-20H-O264	PR
437838	WELL	PR	06/01/2023	OW	123-39725	Dale 4H-20H-O264	TA
437839	WELL	PR	06/01/2023	OW	123-39726	Dale 4G-20H-O264	TA
437840	WELL	PR	06/01/2023	OW	123-39727	Dale 4I-20H-O264	TA
437841	WELL	PR	05/01/2018	OW	123-39728	Dale 4C-20H-O264	PR
437842	WELL	PR	06/01/2023	OW	123-39729	Dale 4J-20H-O264	TA
437843	WELL	PR	06/01/2023	OW	123-39730	Dale 4D-20H-O264	TA
437844	WELL	PR	06/01/2023	OW	123-39731	Dale 4F-20H-O264	TA
437849	WELL	PR	06/01/2023	OW	123-39733	Dale 4K-20H-O264	TA
437856	WELL	PR	03/15/2015	OW	123-39738	Dale 4A-20H-O264	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Bulk tank needs sign/ Label contents and NFPA placard. See attached photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/01/2023

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 4		
Comment:	2 sheds		
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 437836 Type: WELL API Number: 123-39723 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/14/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 437837 Type: WELL API Number: 123-39724 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/14/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 437838 Type: WELL API Number: 123-39725 Status: PR Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/14/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 437839 Type: WELL API Number: 123-39726 Status: PR Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 02/14/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 437840 Type: WELL API Number: 123-39727 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 02/14/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 437841 Type: WELL API Number: 123-39728 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 02/14/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 437842 Type: WELL API Number: 123-39729 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 02/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 437843 Type: WELL API Number: 123-39730 Status: PR Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder:

Comment: T/A

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 437844 Type: WELL API Number: 123-39731 Status: PR Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder:

Comment: T/A

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 437849 Type: WELL API Number: 123-39733 Status: PR Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder:

Comment: T/A

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/14/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 437856 Type: WELL API Number: 123-39738 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 02/14/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday 10/18/23 at approximately 1200hrs I, Inspector Adam Burns, Conducted an on-site inspection at Dale 20H-O264 Well's Location of Civitas. Location ID: 437845 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Bulk tank needs sign/ Label contents and NFPA placard. Install sign to comply with Rule 605.h. With a Corrective Action date of 12/1/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	10/19/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107635	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6291030