

Inspection Photos
Location Name: HOLMAN-65N64W/14SWNE
Location ID: 323370



Photo #1
Holman 14-1 Battery site
Inactive | Shut-down
Tank(s): SE corner



Photo #2
Holman 14-1 Battery site
Inactive | Shut-down
Separator(s)



Inspection Photos
Location Name: HOLMAN-65N64W/14SWNE
Location ID: 323370



Photo #3

Holman 14-1 Battery site
Inactive | Shut-down
Separator(s) produced H2O vault
CA: Overgrown Vegetation



Photo #4

Holman 14-1 Battery site
Inactive | Shut-down
Battery sign



Inspection Photos
Location Name: HOLMAN-65N64W/14SWNE
Location ID: 323370



Photo #5
Holman 14-1 (123-12922) Wellsite
Temporarily Abandoned | TA

