

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 22-18 Pad

Location ID: 335810



Photo # 2914 From entrance to location



Photo # 2915 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 22-18 Pad

Location ID: 335810




Photo # 2916 Location



Photo # 2917 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 22-18 Pad

Location ID: 335810



Photo # 2918 Location



Photo # 2919 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 22-18 Pad

Location ID: 335810

Oct 18, 2023 at 11:40:29 AM



Photo # 2920 Location

Oct 18, 2023 at 11:41:34 AM



Photo # 2921

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 22-18 Pad

Location ID: 335810



Photo # 2922 Debris



Photo # 2923 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 22-18 Pad

Location ID: 335810



Photo # 2924 Tank label has incorrect capacity

Photo # 2925