

Operator: 8 North

Location Name: DF RANCH PC GK02-77HN

Loc ID: 428119

Inspection: 696305279



Exhibit A



Exhibit B

CA: Label missing on Container at Wellhead; see photos. Install sign to comply with Rule 605.h.

CA Resolution: The container identified at the Wellhead has been addressed and completely removed from the location.