

Inspection Photos
Location Name: HER_43-5
Location ID: 320498



Photo #1 location sign.

Photo #2 Crude tank.

Inspection Photos
Location Name: HER_43-5
Location ID: 320498



Photo #3 Well head (1887.72 feet) from location.

Photo #4 stained soil in berm.

Inspection Photos
Location Name: HER_43-5
Location ID: 320498



Photo #5 P/W tank.

Photo #6 Separator.

Inspection Photos
Location Name: HER_43-5
Location ID: 320498



Photo #7 Separator.



Photo #8 Well head (no sign).

Inspection Photos
Location Name: HER_43-5
Location ID: 320498



Video #1 Gas imaging video of well head leaking.




Photo #9 Distance from well head to location (1887.72 feet).