

WELL NAME: HILL RANCH 33-13 R & V, API #: 071-06907, INSP. # 695108686



PHOTO 1: WELL SIGN



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: WELL SIGN



PHOTO 4: LOCATION.





PHOTO 4: LOCATION.





PHOTO 5: AREA OF IMPACTED SOIL NEAR R WELL PRIME MOVER. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. **COMPLY WITH RULE 1002,(2).D. CA DATE 11-20-2023.**





PHOTO 6: OILY WASTE IN ENGINE SKID. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 10-21-2023.

