

WELL NAME: HILL RANCH 32-8, API #: 071-08062, INSP. # 695108689



PHOTO 1: WELL SIGN





**PHOTO 2: LOCATION**





**PHOTO 3: WELLHEAD AND EQUIPMENT**



**PHOTO 4: Signs of recent slow leak from wellhead. Salt/mineral buildup is evident on the wellhead and ground around wellhead. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals, remove salt/mineral buildup, maintain in good mechanical condition remove and dispose of impacted material per Rule 608.e. ca date 11-20-2-23.**





**PHOTO 5: OILY WASTE IN ENGINE SKID. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. ca date 10-23-2023.**

