

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV/26-28

Location ID: 335071

Date: 10/17/2023



Location Entrance – Photo #07038

Wellheads – Photo #07039

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV/26-28

Location ID: 335071

Date: 10/17/2023



Separators – Photo #07042

Tank Battery – Photo #07045

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV/26-28

Location ID: 335071

Date: 10/17/2023



Debris – Photo #07040



Open-Ended Load Line – Photo #07043

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV/26-28

Location ID: 335071

Date: 10/17/2023



Open-Ended Vent Line – Photo #07044



Lack of Stabilization – Photo #07041

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV/26-28

Location ID: 335071

Date: 10/17/2023



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #07050