




TANK BATTERY DECOMMISSIONING FORM

SITE NAME: Aspen Abbey State V16-75HN O SA							DATE: 10/19/2023	REM. PROJECT #:	WEATHER: 60s Sunny	
SITE DIRECTIONS: CR 20,19. W 4 miles, site on right on side of road							CLIENT: Oxy			
LEGALS AND LAT/LONG: (40.1315424, -104.8995266)							TASMAN PERSONNEL: A TRAN			
SOIL TYPES: Clayey Sand - SC							SURFACE GRADIENT: South			
SOIL SAMPLING							FACILITY INFRASTRUCTURE			
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity	
							Above Ground Storage Tank (AST)			
10/19/2023 11:40	AST-B01@3"	1.9	No Staining	No Odor	Yes	N/A	Buried or Partially Buried Vessel			
10/19/2023 11:42	AST-B02@3"	2.7	No Staining	No Odor	Yes	Lab	Separator			
10/19/2023 11:44	AST-B03@3"	1.9	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)			
10/19/2023 11:46	AST-B04@3"	2.5	No Staining	No Odor	Yes	Lab	Dump Line			
10/19/2023 11:48	AST-B05@3"	1.2	No Staining	No Odor	Yes	N/A	Wellhead			
10/19/2023 11:50	AST-B06@3"	3.9	No Staining	No Odor	Yes	Lab	Flowline			
10/19/2023 11:52	AST-B07@3"	0.5	No Staining	No Odor	Yes	N/A	Other:			
10/19/2023 11:54	AST-B08@3"	1.0	No Staining	No Odor	Yes	Lab	Soil Loads Removed			
10/19/2023 11:56	BG01@3"	0.5	No Staining	No Odor	Yes	Lab	IMPACTED SOIL IDENTIFIED?			
10/19/2023 11:58	BG02@3"	0.6	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:			
10/19/2023 12:00	BG03@3"	0.4	No Staining	No Odor	Yes	Lab	Date	Number	CY	
10/19/2023 12:02	BG04@3"	0.2	No Staining	No Odor	Yes	Lab				
10/19/2023 12:04	BG05@3"	0.3	No Staining	No Odor	Yes	Lab				
10/19/2023 12:06	AST-B09@3"	0.9	No Staining	No Odor	Yes	N/A				
10/19/2023 12:08	AST-B10@3"	1.7	No Staining	Slight HC Odor	Yes	Lab				
							Total Removed		0 0	
							Disposal Facility:			
							Groundwater Recovery			
							DATE GW ENCOUNTERED:		DEPTH:	
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?			
							LNAPL OR SHEEN OBSERVED ON GW?			
GROUNDWATER SAMPLING							Date		BBLs	
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?				
							Total Removed		0	
							Disposal Facility:			

Photographic Log

								
						Equipment ID:		
Material:		Volume:	Contents:		Equipment ID:		Equipment Type:	
Notes/Conditions:			Notes/Conditions:					

Photographic Log



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log



Equipment ID:			Equipment Type:			Equipment ID:			Equipment Type:		
Material:		Volume:	Contents:			Material:		Volume:	Contents:		
Notes/Conditions:						Notes/Conditions:					

Photographic Log

						
						Equipment ID:
Material:		Volume:	Contents:		Notes/Conditions:	
Material:		Volume:	Contents:		Notes/Conditions:	