

**State of Colorado**  
**Energy & Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



|                                      |
|--------------------------------------|
| <b>OGCC RECEPTION</b>                |
| Receive Date:<br><b>06/23/2023</b>   |
| Document Number:<br><b>403443886</b> |

**ANALYTICAL SAMPLE DATA SUBMITTAL FORM**

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

**Operator Information**

|  |   |
|--|---|
| OGCC Operator Number: <u>10330</u>                           | Contact Person: <u>Brent Bongers</u>      |
| Company Name: <u>INVESTMENT EQUIPMENT LLC</u>                | Phone: <u>(361) 935-5633</u>              |
| Address: <u>558 CASTLE PINES PKWY UNIT B-4</u>               | Fax: <u>( )</u>                           |
| City: <u>CASTLE PINES</u> State: <u>CO</u> Zip: <u>80108</u> | Email: <u>bbongers@vedolaresoures.com</u> |

**Identification Information**

|  |                                 |  |
|--|---------------------------------|--|
| API Number: 05 - <u>    </u> - <u>    </u>         | OGCC Facility ID: <u>107546</u> | Initial Form 19 or 27 Document number: <u>    </u> |
| Facility Name: <u>DAVIS 1</u>                      | Facility Number: <u>    </u>    | Facility Type: <u>PIT</u>                          |
| Location QtrQtr: <u>SWNE</u>                       | Section: <u>30</u>              | Township: <u>3S</u>                                |
|  | Range: <u>51W</u>               | Meridian: <u>6</u>                                 |
|  | County: <u>WASHINGTON</u>       | Field Name: <u>RANGER</u>                          |
| Federal, Indian or State Lease Number: <u>    </u> |                                 |  |

Information Submitted By:

|                                   |                                     |                               |
|-----------------------------------|-------------------------------------|-------------------------------|
| Company Name: <u>CGRS, Inc.</u>   | Agent Name: <u>Drezden Kinnaird</u> | Title: <u>Project Manager</u> |
| Phone Number: <u>970-493-7780</u> | Email: <u>dkinnaird@cgrs.com</u>    |                               |

Rule 909.J Inspection Information

Date the Pit was Inspected 05/10/2023

On inspection the Pit was:  Unlined     Lined     Fenced     Netted

**Sample Location Information:**

The following Sample Locations have been reviewed by COGCC Staff:

|                                |                               |   |
|--------------------------------|-------------------------------|---|
| Facility ID: <u>771019</u>     | Facility Name: <u>Davis 1</u> | Facility Type: <u>Oil/Gas Production Facility</u> |
| Location: QtrQtr: <u>SWNE</u>  | Sec: <u>30</u>                | Twp: <u>3S</u>                                    |
|                                | Range: <u>51W</u>             | Meridian: <u>6</u>                                |
| County Name: <u>WASHINGTON</u> | Latitude: <u>39.764836</u>    | Longitude: <u>-103.128136</u>                     |

**Sample Information:**

The following Sample Information has been reviewed by the COGCC:

|                                 |                                 |  |
|---------------------------------|---------------------------------|--|
| Batch ID: <u>111177</u>         | Document Name: <u>EDD</u>       | File Name: <u>Davis Investment EDD.xls</u>         |
| Sample Type: <u>    </u>        | Matrix: <u>    </u>             |  |
| Facility ID: <u>771019</u>      | Sample ID: <u>649834</u>        | Sample Name: <u>Davis WT- Investment Equipment</u> |
|                                 | Sample Date: <u>05/10/2023</u>  |  |
| Collection Point: <u>PitDis</u> | Matrix: <u>WATER</u>            | Pre Post: <u>Rule 909.j subsequent sample</u>      |
| Project Number: <u>771019</u>   | Remediation Number: <u>    </u> | Complaint Number: <u>    </u>                      |
|                                 |                                 | NOAV Number: <u>    </u>                           |
| Inspection Number: <u>    </u>  | Spill Number: <u>    </u>       | Laboratory: <u>    </u>                            |
|                                 |                                 | Lab Sample ID: <u>AA01066</u>                      |

**Sample Facility Attachment:**

| Facility ID | Attach Num | File Name                     | Document Name     | File Type |
|-------------|------------|-------------------------------|-------------------|-----------|
| 771019      | 403443899  | 20590_2023_0510_DATA - MR.pdf | Field Data Report | PDF       |

|        |           |                                    |                              |     |
|--------|-----------|------------------------------------|------------------------------|-----|
| 771019 | 403443898 | Davis WT Investment Lab Report.pdf | Analytical Laboratory Report | PDF |
|--------|-----------|------------------------------------|------------------------------|-----|

**Sample COGCC Well Related:**

| Sample ID | API Num   | Well Name & Num | Sample Reason                |
|-----------|-----------|-----------------|------------------------------|
| 649834    | 121-05369 | DAVIS W T 2     | Rule 909.j subsequent sample |
| 649834    | 121-05373 | DAVIS W T 3     | Rule 909.j subsequent sample |
| 649834    | 121-05413 | DAVIS W T 1     | Rule 909.j subsequent sample |

**General Comments**

| <u>User Group</u>   | <u>Comment</u>  | <u>Comment Date</u> |
|---------------------|---|---------------------|
| Environmental Data  | The data submitted by the operator can be accessed through the COGIS data system. | 10/23/2023          |
| Total: 1 comment(s) |   |                     |