

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Dutch Lake Pad 16-24H

Loc ID: 422838

Inspection: 696305334



Exhibit A

CA: Vault East of Separators missing Labels - Content, Capacity and NFPA; See photos. Install sign to comply with Rule 605.h.

CA Resolution: Labels regarding Content, Capacity, and NFPA has been updated and installed to comply with Rule 605.h.



Exhibit A

CA: Overgrown Vegetation on Location; see photos. Comply with Rule 606.

CA Resolution: Operator has addressed and cleared overgrown vegetation and weed debris from location to comply with Rule 606.



Exhibit A




Exhibit B



Exhibit C



Exhibit D

CA: Unmarked Risers at ECD, in between Separators and East of Separators; see photos. Comply with Rule 606.

CA Resolution: Operator has marked the identified risers to comply with Rule 606.



Exhibit A



Exhibit B

CA: Stained Soil at Riser Area East of Separators; see photos. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Operator has appropriately addressed and cleaned identified areas of stained soil to comply with Rule 905.e.