

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: CB Rudd 6-61-18_19 SW7

Loc ID: 438823

Inspection: 696305339



Exhibit A

CA: Condensate Vault at VRU missing Capacity Label; see photos. Install sign to comply with Rule 605.h.

CA Resolution: Labels regarding Content, Capacity, and NFPA has been updated and installed to comply with Rule 605.h.



Exhibit A



Exhibit B



Exhibit C




Exhibit D



Exhibit E

CA: Tumbleweeds around Tank Berm; see photos. Comply with Rule 606.

CA Resolution: Operator has addressed and cleared tumbleweeds and other weed debris from location to comply with Rule 606.

CA: Stained Soil at NW Corner of Tank Berm; see photos. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Operator has appropriately addressed and cleaned identified areas of stained soil to comply with Rule 905.e.