

# Final Reclamation Inspection

October 23th, 2023

Operator: Hilcorp Energy Company - 10133

Location ID: 385910

Inspection Document #: 714000060

La Plata County, CO

Township: NESE 312 34N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Kaime 2-12 UR  
Location ID: 385910



**Photo 1.** View southwest project facing center. Note: this side of the location has not been reclaimed.

Inspection Photos  
Location Name: Kaime 2-12 UR  
Location ID: 385910



**Photo 2.** View of the northern project area taken from the center of the disturbance facing northwest.

Inspection Photos  
Location Name: Kaime 2-12 UR  
Location ID: 385910



**Photo 3.** Reference area comprised of smooth brome and crested wheatgrass.