

Inspection Photos

Location Name:

WASTE MANGEMENT USX Y-62N64W 3NWSW Tank Battery

Location ID: 306503



Production Equipment



Tank Battery

Inspection Photos

Location Name:

WASTE MANGEMENT USX Y-62N64W 3NWSW Tank Battery

Location ID: 306503



Unmarked risers need to be marked by identifying what they are and tagged with OOSLAT. "LOTO"

Unmarked risers need to be marked by identifying what they are and tagged with OOSLAT. "LOTO"

Inspection Photos

Location Name:

WASTE MANGEMENT USX Y-62N64W 3NWSW Tank Battery

Location ID: 306503



Unused Panel Fence