

Inspection Photos
Location Name: Waste Management USX Y 3-19
API # 05-123-24387



Location

Unused equipment and riser needs to be identified