

Inspection Photos

Location Name: Guttersen-63N64W 33SWSE Tank Battery

Location ID: 305392



Tank Battery and tumble weeds



Unused sign frame and tumble weeds

Inspection Photos
Location Name: Gutteresen-63N64W 33SWSE Tank Battery
Location ID: 305392



Tumble weeds



Tumble weeds


Inspection Photos

Location Name: Gutteresen-63N64W 33SWSE Tank Battery

Location ID: 305392



Unmarked Riser



Unmarked Riser

Inspection Photos

Location Name: Guttersen-63N64W 33SWSE Tank Battery

Location ID: 305392



Unmarked Riser



Production equipment and tumble weeds

Inspection Photos

Location Name: Guttersen-63N64W 33SWSE Tank Battery

Location ID: 305392



Tumble weeds



Tumble weeds

Inspection Photos

Location Name: Guttersen-63N64W 33SWSE Tank Battery

Location ID: 305392



Tumble weeds



Tumble weeds