



**Inspected Facilities**

Facility ID: 286682 Type: WELL API Number: 071-08977 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR](#)

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">THIS IS A FOLLOW UP TO INSP. DOC#695108577. BASED ON PHOTOS SUBMITTED IN FIRR DOC #403508345 CA'S HAVE BEEN ADDRESSED.</a>	beardsit	10/24/2023