

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESE

Location ID: 334760

Date: 10/24/2023



Location Entrance – Photo #07111



Wellheads – Photo #07113

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESE

Location ID: 334760

Date: 10/24/2023



Separators – Photo #07116



Tank Battery – Photo #07117

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NESE

Location ID: 334760

Date: 10/24/2023



Lack of Stabilization – Photo #07112



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #07115**