

Inspection Photos
Location Name: John A. Kunzman #1
Location ID: 317729



Photo 1 Location.



Photo 2 WH sign.

Inspection Photos
Location Name: John A. Kunzman #1
Location ID: 317729



Photo 3 WH.




Photo 4 Dead vegetation around unused fencing for old ancillary equip.

Inspection Photos
Location Name: John A. Kunzman #1
Location ID: 317729



Photo 5 Dead vegetation around unused pump jack.



Photo 6 Dead vegetation around unused pump jack base and concrete.

Inspection Photos
Location Name: John A. Kunzman #1
Location ID: 317729




Photo 7 Dead vegetation around unused pump jack.



Photo 8 Dead vegetation around unused pump jack base and concrete.

Inspection Photos
Location Name: John A. Kunzman #1
Location ID: 317729



Photo 9 Dead vegetation around WH.




Photo 10 Dead vegetation around unused pump jack base and concrete.