

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2023

Submitted Date:

10/24/2023

Document Number:

701007561

**FIELD INSPECTION FORM**

Loc ID 337480 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286200	WELL	PR	08/01/2019	GW	125-10258	ALLEN 13-7	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	Two track through pasture	
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type	WELLHEAD	
	Comment:	Lease sign by wellhead	
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type	PUMP JACK	
	Comment:	Metal panels around unit and wellhead	
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
	Comment:	Weatherford unit	
Corrective Action:			Date:
Type: Prime Mover	# 1		
	Comment:	Kohler gas engine	
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
	Comment:	Gas scrubber and telemetry equipment	
Corrective Action:			Date:
Type: Vertical Separator	# 1		
	Comment:	Vertical gas separator 50% buried by meter run	
Corrective Action:			Date:

<b>Venting:</b>			
	Yes/No		
	Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 286200 Type: WELL API Number: 125-10258 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT