

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY 11-34 Pad

Location #: 324174



Photo # 4028 From entrance to location



Photo # 4029 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY 11-34 Pad

Location #: 324174



Photo # 4030 Location




Photo # 4031 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY 11-34 Pad

Location #: 324174



**Photo # 4032 Flowline heating insulation open ended**



**Photo # 4033 Flowline heating insulation open ended**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY 11-34 Pad

Location #: 324174



**Photo # 4034 Flowline heating insulation open ended**



**Photo # 4035 Flowline heating insulation open ended**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENTLEY 11-34 Pad

Location #: 324174




Photo # 4036 Battery sign does not list BENTLEY 11-34 well/  
well info

