


**Inspection Photos**  
**Location Name: Hopkins 41C – 19 # 2**  
**Location ID: 317973**



**Photo 1 well head and equipment**



**Photo 2 well head and equipment**

**Inspection Photos**  
**Location Name: Hopkins 41C – 19 # 2**  
**Location ID: 317973**



**Photo 3 production equipment**



**Photo 4 production equipment**

Inspection Photos  
Location Name: Hopkins 41C – 19 # 2  
Location ID: 317973



Photo 5 gas sales meter tube



Photo 6 tank battery sign

**Inspection Photos**  
**Location Name: Hopkins 41C – 19 # 2**  
**Location ID: 317973**



**Photo 7 south side of crude tank**



**Photo 8 south side of crude tank**

**Inspection Photos**  
**Location Name: Hopkins 41C – 19 # 2**  
**Location ID: 317973**



**Photo 9 tank battery**



**Photo 10 north side of crude tank**

**Inspection Photos**  
**Location Name: Hopkins 41C – 19 # 2**  
**Location ID: 317973**



**Photo 11 east side of crude tank**



**Photo 12 soiled area between tanks east side**

Inspection Photos  
Location Name: Hopkins 41C – 19 # 2  
Location ID: 317973



Photo 13 west side of crude tank



Photo 14 landing at thief hatch