

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646




Photo 1 well head and equipment, 2 vacant risers



Photo 2 well head and equipment

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646



Photo 3 electrical service panel



Photo 4 produced water tank and vacant 3" riser

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646



Photo 5 meter run



Photo 6 vacant 3" riser at meter run

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646



Photo 7 production equipment



Photo 8 production equipment

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646



Photo 9 unused equipment abandoned electrical risers



Photo 10 ECD and tank battery

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646



Photo 11 unused equipment and piping



Photo 12 tank battery

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646



Photo 13 tank battery



Photo 14 tank battery

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646



Photo 15 stained soil @ tank battery



Photo 16 stained soil @ tank battery

Inspection Photos
Location Name: August Gittlein 1
Location ID: 317646



Photo 17 vacant 2" riser @ tank battery




Photo 18 meter calibration card 9-2018