

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2023

Submitted Date:

10/26/2023

Document Number:

699107693**FIELD INSPECTION FORM**Loc ID 437845 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437836	WELL	PR	05/01/2018	OW	123-39723	Dale 4E-20H-O264	PR
437837	WELL	PR	03/15/2015	OW	123-39724	Dale 4B-20H-O264	PR
437838	WELL	PR	06/01/2023	OW	123-39725	Dale 4H-20H-O264	TA
437839	WELL	PR	06/01/2023	OW	123-39726	Dale 4G-20H-O264	TA
437840	WELL	PR	06/01/2023	OW	123-39727	Dale 4I-20H-O264	TA
437841	WELL	PR	05/01/2018	OW	123-39728	Dale 4C-20H-O264	PR
437842	WELL	PR	06/01/2023	OW	123-39729	Dale 4J-20H-O264	TA
437843	WELL	PR	06/01/2023	OW	123-39730	Dale 4D-20H-O264	TA
437844	WELL	PR	06/01/2023	OW	123-39731	Dale 4F-20H-O264	TA
437849	WELL	PR	06/01/2023	OW	123-39733	Dale 4K-20H-O264	TA
437856	WELL	PR	03/15/2015	OW	123-39738	Dale 4A-20H-O264	PR

**General Comment:**This is an AMI to FIRR # 403569103. CA has been corrected

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 437836	Type: WELL	API Number: 123-39723	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: pr				
Corrective Action:			Date:	
Facility ID: 437837	Type: WELL	API Number: 123-39724	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: pr				
Corrective Action:			Date:	
Facility ID: 437838	Type: WELL	API Number: 123-39725	Status: PR	Insp. Status: TA
<b>Idle Well</b>				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: t/a				
Corrective Action:			Date:	
Facility ID: 437839	Type: WELL	API Number: 123-39726	Status: PR	Insp. Status: TA
<b>Idle Well</b>				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: t/a				
Corrective Action:			Date:	
Facility ID: 437840	Type: WELL	API Number: 123-39727	Status: PR	Insp. Status: TA
<b>Idle Well</b>				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: t/a				
Corrective Action:			Date:	
Facility ID: 437841	Type: WELL	API Number: 123-39728	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: pr				
Corrective Action:			Date:	
Facility ID: 437842	Type: WELL	API Number: 123-39729	Status: PR	Insp. Status: TA
<b>Idle Well</b>				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: t/a				
Corrective Action:			Date:	

Facility ID: 437843 Type: WELL API Number: 123-39730 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: t/a

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 437844 Type: WELL API Number: 123-39731 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: t/a

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 437849 Type: WELL API Number: 123-39733 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: t/a

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 437856 Type: WELL API Number: 123-39738 Status: PR Insp. Status: PR

**Producing Well**

Comment: pr

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107694	Civitas Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6299346">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6299346</a>