

## Inspection Photos

Location Name: WHITE-65N64W/34NWNW

Location ID: 322785



**Photo #1**

**White 34-2 (123-12050) Wellsite**

**Shut-In | SI**

**CA: Overgrown Vegetation**

*prior photo*



**Photo #2**

**White 34-2 Wellsite**

**Shut-In | SI**

**Overgrown Vegetation: Mitigated**

*Photo: Operator provided*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: WHITE-65N64W/34NWNW

Location ID: 322785



### Photo #3

White 34-2\*, 34-1, 1-1

Battery site *prior photo*

**Inactive | Shut-down**

*Formerly served:*

*White 12-34, 27-4, Bettale 34-1 ;*

*Plugged & Abandoned | PA*

***Equipment Documented; Loc ID: 322785***



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources