

Inspection Photos
Location Name: WHITE-65N64W/34NWNW
Location ID: 305926



Photo #1

White 1-1 (123-23689) Wellsite

Temporarily Abandoned | TA

CA: Overgrown Vegetation

prior photo



Photo #2

White 1-1 Wellsite

Temporarily Abandoned | TA

Overgrown Vegetation: Mitigated

Photo: Operator provided



Inspection Photos

Location Name: WHITE-65N64W/34NWNW

Location ID: 305926



Photo #3

White 34-2*, 34-1, 1-1

Battery site

Inactive | Shut-down

Formerly served:

White 12-34, 27-4, Bettale 34-1 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 322785



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources