

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/25SWSW

Location ID: 335097

Date: 10/26/2023



Location Entrance – Photo #07190



Wellheads – Photo #07189

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/25SWSW

Location ID: 335097

Date: 10/26/2023



Separators – Photo #07191



Tank Battery – Photo #07194

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/25SWSW

Location ID: 335097

Date: 10/26/2023



Open-Ended Load Line – Photo #07193